

00862.021692.

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

AOJI ISONO ET AL.

Appln. No.: 09/719,523

Filed: October 5, 1999

For: METHOD OF CONTROLLING
IMAGE DISPLAY

U.S. Patent No.: 6,972,741 B1

Issued: December 6, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION *777-73556 50E95081 890009126 6372741*
UNDER RULES 322 AND 323

100-000-00


Sir.

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 570560v1

JUL 31 2006

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1
DATED : December 6, 2005
INVENTOR(S) : AOJI ISONO ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents:

“3055738 3/1991” should read --3-055738 3/1991--;
“4028137 1/1992” should read --4-028137 1/1992--;
“2257551 10/1990” should read 2-257551 10/1990--;
“1031332 2/1989” should read --1-031332 2/1989--;
“03048889 1/1991” should read --03-048889 1/1991--;
“04204993A 7/1992” should read --04-204993A 7/1992--;
“02273720 8/1990” should read --02-273720 8/1990--;
“02272490 7/1990” should read --02-272490 7/1990--;
“0 707 301 A1 4/1976” should read --0 707 301 A1 4/1996--; and

Other Publications after “Physical”:

“Emisssion” should read --Emission-- and
“Molybedium” should read --Molybdenum--.

SHEET 5:

Figure 5, “LIMINANCE” should read --LUMINANCE--.

SHEET 6:

Figure 6, “REGURATOR” should read --REGULATOR-- and
“RAGURATOR” should read --REGULATOR--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page



JUL 31 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1
DATED : December 6, 2005
INVENTOR(S) : AOJI ISONO ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 7:

Figure 7, "REGURATOR" should read --REGULATOR-- and
"RAGURATOR" should read --REGULATOR--.

COLUMN 1:

Line 2, "DISPLAY" should read --DISPLAY ¶TECHNICAL FIELD--.

COLUMN 2:

Line 8, "denium" should read --denum--.

COLUMN 3:

Line 12, "Microele-ctronics" should read --Microelectronics--.

COLUMN 4:

Line 21, "3kv" should read --3kV--.

COLUMN 6:

Line 57, "while" should read --while an image--.

COLUMN 15:

Line 51, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1

DATED : December 6, 2005

INVENTOR(S) : AOJI ISONO ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "step s47." should read --step S47.--.

COLUMN 28:

Line 54, "show" should read --shows--.

COLUMN 33:

Line 9, "take" should read --taken--.

COLUMN 34:

Line 1, "for" should read --that--;

Line 19, "character graphic" should read --character-graphic--; and

Line 22, "character graphic" should read --character-graphic--.

COLUMN 36:

Line 37, "source; an" should read --source; ¶ an--; and

Line 65, "source; an" should read --source; ¶ an--.

COLUMN 37:

Line 18, "comprising" should read --comprises--;

Line 27, "source; an" should read --source; ¶ an--;

Line 47, "comprising" should read --comprises--; and

Line 51, "connect" should read --connected--.

Line 56, "source; an" should read --source; ¶ an--;

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page



1111 2222 4444

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1

DATED : December 6, 2005

INVENTOR(S) : AOJI ISONO ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38:

Line 14, "shutdown" should read --shutdown,--;

Line 19, "comprising" should read --comprises--;

Line 28, "source; an" should read --source; ¶ an--;

Line 41, "battery;" should read --battery; and--; and

Line 50, "source-comprising" should read --source comprises--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page



JULY 31 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1
DATED : December 6, 2005
INVENTOR(S) : AOJI ISONO ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents:

“3055738 3/1991” should read --3-055738 3/1991--;
“4028137 1/1992” should read --4-028137 1/1992--;
“2257551 10/1990” should read 2-257551 10/1990--;
“1031332 2/1989” should read --1-031332 2/1989--;
“03048889 1/1991” should read --03-048889 1/1991--;
“04204993A 7/1992” should read --04-204993A 7/1992--;
“02273720 8/1990” should read --02-273720 8/1990--;
“02272490 7/1990” should read --02-272490 7/1990--;
“0 707 301 A1 4/1976” should read --0 707 301 A1 4/1996--; and

Other Publications after “Physical”:

“Emisssion” should read --Emission-- and
“Molybedium” should read --Molybdenum--.

SHEET 5:

Figure 5, “LIMINANCE” should read --LUMINANCE--.

SHEET 6:

Figure 6, “REGURATOR” should read --REGULATOR-- and
“RAGURATOR” should read --REGULATOR--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page

JUL 31 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1
DATED : December 6, 2005
INVENTOR(S) : AOJI ISONO ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 7:

Figure 7, "REGURATOR" should read --REGULATOR-- and
"RAGURATOR" should read --REGULATOR--.

COLUMN 1:

Line 2, "DISPLAY" should read --DISPLAY ¶TECHNICAL FIELD--.

COLUMN 2:

Line 8, "denium" should read --denum--.

COLUMN 3:

Line 12, "Microele-ctronics" should read --Microelectronics--.

COLUMN 4:

Line 21, "3kv" should read --3kV--.

COLUMN 6:

Line 57, "while" should read --while an image--.

COLUMN 15:

Line 51, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1
DATED : December 6, 2005
INVENTOR(S) : AOJI ISONO ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "step s47." should read --step S47.--.

COLUMN 28:

Line 54, "show" should read --shows--.

COLUMN 33:

Line 9, "take" should read --taken--.

COLUMN 34:

Line 1, "for" should read --that--;

Line 19, "character graphic" should read --character-graphic--; and

Line 22, "character graphic" should read --character-graphic--.

COLUMN 36:

Line 37, "source; an" should read --source; ¶ an--; and

Line 65, "source; an" should read --source; ¶ an--.

COLUMN 37:

Line 18, "comprising" should read --comprises--;

Line 27, "source; an" should read --source; ¶ an--;

Line 47, "comprising" should read --comprises--; and

Line 51, "connect" should read --connected--.

Line 56, "source; an" should read --source; ¶ an--;

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,972,741 B1

DATED : December 6, 2005

INVENTOR(S) : AOJI ISONO ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38:

Line 14, "shutdown" should read --shutdown,--;

Line 19, "comprising" should read --comprises--;

Line 28, "source; an" should read --source; ¶ an--;

Line 41, "battery;" should read --battery; and--; and

Line 50, "source-comprising" should read --source comprises--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,972,741 B1

No. of add'l. copies
@ 30¢ per page

